

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4610	DATE	Nov.20.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On the four-wheel drive vehicles, due to an improper tightening of the clutch tube during tightening process, there is a possibility that the gap between the tube and a front propeller shaft is narrow. If this were to occur, the tube will contact with the front propeller shaft on the condition such as vibration during vehicle use, and damage, resulting in leak of the clutch oil, and in the worst case, the vehicle could lose shift control.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDF-KDY271	[DYNA]	2019	26
LDF-KDY281	[TOYOACE]		68
		TOTAL	94