

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4602	DATE	Nov.21,2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper construction of the engine auxiliary belt, the durability of the belt may be insufficient and the belt may break down with the resonance fracture. If belt breaks down, the alternator and the water pump become inoperative with the warning lamp turned on. In the worst scenario, engine may stall and may not restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MK32S	SPACIA	2014	5,887
DBA-MM32S	FLAIR WAGON		1,014
		TOTAL	6,901