

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4605	DATE	Nov.21,2019
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to improper length of brake hose at the front brake line, tensile force may be applied to the brake hose and crack may be developed inside the brake hose.</p> <p>If the vehicle is being used in such condition, the crack could further develop, resulting in the brake fluid leakage and the brake warning light turning on. In the worst case, braking force could be reduced.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-MK21S	PALETTE	2008~2013	276,593
CBA-MK21S			61,429
DBA-ML21S	ROOX	2009~2013	164,021
CBA-ML21S			9,373
DBA-MM21S	FLAIR WAGON	2012~2013	5,776
CBA-MM21S			124
		TOTAL	517,316