

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4615	DATE	November 21, 2019	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to the 130A alternator power supply wiring, some of the power supply wires may interfere with the fixing bracket edge because of an inappropriate routing and attachment method for the back side of the alternator, which may lead to the wire cover may becoming damaged from vehicle vibration. Thus, if the vehicle continues operation under these conditions, the power supply wiring may cause a short-circuit after which the wire may have a risk of generating heat and smoke.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	Quon	2017 - 2019	17	
2PG-CD5BA		2017 - 2019	115	
2PG-CD5BL 2PG-CD5BLKai		2017 - 2019	154	
2PG-CD5CA 2PG-CD5CAKai		2017 - 2019	2095	
2PG-CD5CE		2018 - 2019	158	
2PG-CD5CL		2017 - 2019	185	
2DG-CF5AL		2018	1	
2PG-CG5BA		2017 - 2019	29	
2PG-CG5BE 2PG-CG5BEKai		2018	4	
2PG-CG5BL		2018 - 2019	3	
2PG-CG5CA		2017 - 2019	3817	
2PG-CG5CE		2018 - 2019	204	
2PG-CG5CL		2017 - 2019	162	
2PG-CW5AL		2017 - 2019	1001	
2PG-CW5BL 2PG-CW5BLKai		2017 - 2019	189	
2PG-CW5CA 2PG-CW5CAKai		2017 - 2019	164	
2PG-CW5CL 2PG-CW5CLKai		2017 - 2019	236	
2PG-CX5BA		2017 - 2019	44	
2PG-CX5BL		2017 - 2019	42	
2DG-CZ5BL		2018	1	
2PG-GK5AAB 2PG-GK5AABKai		2017 - 2019	1528	
2PG-GK5AAD		2017 - 2019	519	
2PG-GK5AAE		2017 - 2019	117	
2PG-GK5AAK	2018	1		
2DG-SZ5BL	—	2018	2	
		TOTAL	10788	