VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

	<u> </u>				
CAMPAIGN No.	4617	DATE	November	26. 2019	
MANUFACTURE	Topre Corporation				
DESCRIPTION OF DEFECT	In the spare tire hoisting device mounting bracket of the refrigerated car, there are some portions that are not welded due to inappropriate production management. For that reason, it is expected that the bracket may crack due to vibration during driving, in the worst case, the bracket may break and the bracket and the spare tire may fall off.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
IIFL	NAME	RECALLED	VEHICLE
BDG-FD8JLWG		2011	7
BDG-FD8JMWA		2011	1
BKG-FC7JHYA	HINORANGER	2011	1
BKG-FC7JJYA		2011	4
BKG-FC7JJYG		2011	3
BKG-FC7JKYG		2011	5
BKG-FC7JLYA		2011	2
BKG-FD7JLYA		2011	1
BKG-FD7JKYA		2011	1
BKG-FD7JKYG		2011	1
BKG-FD7JLYG		2011	3
SKG-FC7JJAA		2011	3
SKG-FC7JKAG		2011	2
SKG-FC7JLAA		2011	1
SKG-FC9JKAA		2011	2
SKG-FD7JKAA		2011	2
PDG-FK61F		2011	3
PDG-FK64F	FUSOFIGHTER	2011	2
PDG-FK71R		2011	4
PDG-FK74F		2011	1
SKG-FK61F		2011	1
SKG-FK64F		2011	4
SKG-FK71F		2011	3
SKG-FK74F		2011	3
BDG-MK36C	CONDOR	2011	6
BDG-MK36D	COMPOR	2011	1
BDG-MK37D		2011	1
SKG-MK38C		2011	10
SKG-MK38L		2011	4
		TOTAL	82