

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2962	DATE	Nov. 27, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The collar of the wheel arch cover can become detached due to a torsional movement. As a result, the wheel arch cover may come loose and, in individual cases, become detached from the vehicle.</p> <p>The wheel arch cover must then be serviced with new modified clips.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FYCWGA	Audi SQ5 Air suspension	2019	101
ABA-FYCWGS	Audi SQ5	2018-2019	553
DBA-FYDAXA	Audi Q5 45Tq Air suspension	2018-2019	572
DBA-FYDAXS	Audi Q5 45Tq	2017-2019	2,761
LDA-FYDETA	Audi Q5 40TDIq Air suspension	2019	288
LDA-FYDETS	Audi Q5 40TDIq	2019	1,751
		Total	6,026