

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	4621	DATE	Dec. 2. 2019,
MANUFACTURER	Hino Engineering Annex Co., Ltd.		
DESCRIPTION OF DEFECT	On medium-duty trucks in which the lighting circuit for clearance lamps, license plate lights, and tail lights (hereinafter, "clearance lamps, etc.") has been changed, the clearance lamps, etc. do not light up when headlights are turned on by the auto lighting function due to inappropriate circuit design relevant to the change. Therefore, the vehicles do not conform to safety standard No. 34 (Standard for clearance lamps), etc.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FC2ABA	[HINO Ranger]	2019	9
2KG-FC2ABG		2019	1
		TOTAL	10