

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4623	DATE	December 10, 2019
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the electric forklift, due to lack of strength, brackets which support transformer for battery charging may be deformed or broken by the vibration from road surface. If it is continuously used in the state, the transformer may drop from the chassis, in the worst case, may contact with the power cables, create short cut circuit between these parts and may cause fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
244AA	TRANSER	2004 ~ 2016	6
254AA		2007 ~ 2018	5
		TOTAL	11