

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4624	DATE	Dec.11.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the combination meter containing a speedometer and an odometer, due to improper maintenance of a manufacturing equipment used for production of an element on the circuit board of the meter, there is a possibility that a crack could develop inside of the element. In this condition, electrical short circuit could occur in the element during normal vehicle usage, causing the speedometer and the odometer to become inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-ZVW51	[PRIUS]	2019	6,025
DAA-ZVW55			1,062
		TOTAL	7,087