

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4625	DATE	Dec. 11. 2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the rear seat belt assemblies, due to an improper adjustment for the assembly equipment, there is a possibility that the spring in the seat belt retractor lock mechanism could have been installed with curved condition. In this condition, the spring could interfere with a component, causing the seat belt not to lock when it is pulled out quickly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AGH30W	[ALPHARD] [VELLFIRE]	2019	3,546
DBA-AGH35W			379
DBA-GGH30W			246
DBA-GGH35W			89
DAA-AYH30W			964
DBA-ZRR80G DBA-ZRR80G “kai”(modified)	[NOAH] [VOXY] [ESQUIRE]		732
DBA-ZRR85G DBA-ZRR85G “kai”(modified)			223
DBA-ZRR80W DBA-ZRR80W “kai”(modified)	[NOAH] [VOXY]		641
DBA-ZRR85W			169
DAA-AXVH70	[CAMRY]		717

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-XZB60 2PG-XZB60	[TOYOTA COASTER]	2019	7
2KG-XZB70 2PG-XZB70			34
2PG-XZB60V	[TOYOTA COASTER BIG VAN]		1
DAA-AXVH70N	[ALTIS]		5
2KG-XZB60M 2PG-XZB60M	[HINO LIESSE II]		4
2KG-XZB70M 2PG-XZB70M			32
2PG-XZB70Y	[HINO LIESSE II BIG VAN]		1
			TOTAL