

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4626	DATE	Dec.11.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the driver knee airbag, due to an improper maintenance of the welding equipment, there is a possibility that the weld of the brackets to the knee airbag housing could be insufficient. If this were to occur, the driver knee airbag will not properly inflate during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AGZ10	[NX300]	2019	10
DBA-AGZ15			4
DAA-AYZ10	[NX300h]		12
DAA-AYZ15			2
		TOTAL	28