

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4627	DATE	Dec.11.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the door locks for the front driver and passenger doors, due to an improper manufacturing operation during assembly process, there is a possibility that the rubber stopper for noise prevention could be installed in the incorrect position. If this were to occur, after repeated opening and closing of the door over time, the rubber stopper will interrupt the door lock system, resulting in the door lock not properly latching, and in the worst case, the door could open while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-NTP10	[JPN TAXI]	2018-2019	6,188
		TOTAL	6,188