

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4632	DATE	December 17 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The subject matter relates to the fuel tank installed on the medium-duty truck. Because the procedure for installing a drain plug to the fuel tank is inappropriate, some of the drain plugs are not tightened properly. Consequently, if continuously used without inspection, fuel may leak from the drain plug.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FRR90S1 2PG-FRR90S2 2PG-FRR90T2 2RG-FRR90S1 2RG-FRR90S2 2RG-FRR90T2	[FORWARD]	2019	396
2RG-FRS90S2		2019	1
2PG-FSR90S2 2PG-FSR90T2 2RG-FSR90S2 2RG-FSR90T2		2019	29
2PG-FTR90U2 2PG-FTR90V2 2RG-FTR90U2 2RG-FTR90V2		2019	49
2KG-FVZ60U2		2019	3
2PG-BRR90S2 2PG-BRR90T2 2RG-BRR90S1 2RG-BRR90S2 2RG-BRR90T2	[CONDOR]	2019	18
2RG-BSR90T2		2019	1
2PG-BTR90V2 2RG-BTR90U2 2RG-BTR90V2		2019	6
2PG-BVR90U2		2019	1
		TOTAL	504

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Fuel Tank	8-98275525-0	2019	16
	8-98355008-1	2019	7
TOTAL			23