

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2966	DATE	Dec. 19. 2019
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On oil hoses of the oil cooler (inlet and outlet) cracks may come up where the oil hose connects with the oil pipe. In case of cracks, a small amount of oil may leak. The oil cooler needs to be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-S10AA	「BMW S1000RR」	2019	64
		TOTAL	64