VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4631	DATE	December 19, 2019	
MANUFACTURER	Mazda Motor Corporation			
DESCRIPTION OF DEFECT	(1)The software of the power control module has a programing error, which may cause to improperly control fuel injection when large amount of fuel vapor enter the combustion chamber. As a result, the amount of fuel injection may be insufficient to maintain proper engine combustion. Engine may ultimately stall during low speed driving.			
	(2)The software of the power control module has a programing error in automatic engine start/stop system operation, which may cause engine not to restart properly if the engine condition determination process is delayed.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-BP5P	- Mazda「MAZDA3」	2019	(1) 7,162 (2) 7,162
5BA-BPFP		2019	(2) 7,990
5BA-DMEP	Mazda「CX-30」	2019	(2) 2,215
		Total	(1) 7,162 (2) 17,367