

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4637	DATE	25 Dec , 2019
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	A component part of the headlamp switch in the dozer shovel is made of material different from the specification due to improper instructions for the manufacturing process. For this reason, the strength of the switch is insufficient. When the switch is operated repeatedly, it may break and the headlamp does not light up in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	「WA80-8」	2019	59
WDP-WA124	「WA100-7」	2017	1146
WDR-WA126	「WA200-7」	2017	217
YDP-WA138	「WA100-8」	2017-2019	931
TOTAL			2353

### Models of vehicles that may be used as service parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SB-W108	「WA100-5」	2003-2010	32
KDP-WA115	「WA100-6」	2010-2014	11
WDP-WA124	「WA100-7」	2014-2016	25
SB-W108	「WA150-5」	2004-2005	2
KDP-WA115	「WA150-6」	2011-2013	3
SC-W109	「WA200-5」	2003-2007	4
EDR-WA105	「WA200-6」	2013	1
WDR-WA126	「WA200-7」	2014-2015	7
SC-W104	「WA270-5」	2006	2
EDR-WA103	「WA270-6」	2008-2012	2
SC-W105	「WA320-5」	2003-2007	7
EDR-WA108	「WA320-6」	2008-2013	3
SB-WR003	「WR12-5」	2008	1
TOTAL			100

Switchs that were shipped as service parts and unknown to which units were used

PARTS NAME	PARTS NUMBER	SHIPPING YEAR	NUMBER OF PARTS
SWITCH	418-43-36124	2017-2019	32
TOTAL			32