

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3756	DATE	February. 21 st , 2024
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to an internal software error, the BMW interaction bar is not robust against voltage dips and the control panel may not respond when operated if the voltage drops. As a result, individual functions such as hazard warning lights, rear window heating and windscreen defrost may fail.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-22EH30	BMW 740i	2022	92
ZAA-52EJ89	BMW i7 xDrive60	2022	4
		TOTAL	96