VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI 3767	DATE	15, Feb, 2024	
MANUFACTURE	SCANIA CV AB / Van Hool nv.			
	(Japanese Importer: SCANIA JAPANA Co. Ltd.)			
DESCRIPTION OF DEFECT	Due to inadequate software in the control unit controlling the lights, only the direction indicator on the left side of the vehicle body flashes irregularly when the doors are locked using the locking switch on the front passenger door. In addition, when the lamp check switch on the driver's control panel is operated, all lights, including the braking and reversing lights, automatically switch on and off in sequence, in violation of safety standards.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	-	2016-2020	49
		TOTAL	49