

**VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN  
JAPAN**

Domestic Vehicles

|                              |   |             |                         |
|------------------------------|---|-------------|-------------------------|
| <b>CAMPAIGN No.</b>          | <b>5441</b>   | <b>DATE</b> | <b>January 25, 2024</b> |
| <b>MANUFACTURER</b>          | <b>SUZUKI MOTOR CORPORATION</b>   |             |                         |
| <b>DESCRIPTION OF DEFECT</b> | <p>In the piping of the brake system, the tightening torque of the flare nuts for fastening the brake pipes to the ABS unit may be insufficient due to improper tightening work of the nuts. If the motorcycle continues to be used in this condition, in the worst case, the loosening of the nut may cause brake fluid leakage and increase the braking distance.</p> |             |                         |

| <b>TYPE</b>   | <b>COMMERCIAL NAME</b> | <b>MODEL YEAR RECALLED</b> | <b>NUMBER OF VEHICLE</b> |
|---------------|------------------------|----------------------------|--------------------------|
| <b>SUZUKI</b> | <b>HAYABUSA</b>        | <b>2023</b>                | <b>582</b>               |
|               |                        | <b>TOTAL</b>               | <b>582</b>               |