

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5437	DATE	January. 26. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SC79	「Gold Wing」	2018 ~ 2022	2,447
8BL-SC79	「Gold Wing Tour」	2022 ~ 2023	567
2BL-SC77	「CBR1000RR」	2017 ~ 2020	482
TOTAL			3,496

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS	PART No.	DELIVERED AS "SERVICE PARTS"	NUMBER OF PARTS	NOTE
MODULE ASSY., FUEL PUMP	16700-MFJ-D02	2017 ~ 2020	104	「CBR600RR」
	16700-MKF-D41		67	「CBR1000RR」
	16700-MKC-A01	2020	2	「Gold Wing」 「Gold Wing Tour」
TOTAL			173	