

## VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

### Domestic Vehicles

CAMPAIGN No.	5438	DATE	Jan. 26, 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	The fuel feeding impeller in the fuel pump, which is made of the resin material, may be swollen and deformed in fuel due to the insufficient material density caused by the improper injection molding process. The impeller may interfere with the fuel pump housing, resulting in the fuel pump malfunction. In the worst case, it could cause the engine stalling while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
DAA-MN71S	XBEE	2017~2019	34,165	
3BA-JB64W			22,264	
3BA-JB74W			8,510	
		<b>TOTAL</b>	<b>64,939</b>	

The affected parts shipped as spare parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
DBA-MK32S (revision)	SPACIA	2013	1	The Vehicle with a boarding slope device for wheelchairs
DBA-MA15S	SOLIO	2013~2015	20	
DBA-ZC72S	SWIFT	2013~2015	16	
DBA-ZD72S		2014~2015	5	

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLES</b>	<b>NOTE</b>
<b>DBA-MB15S</b>	<b>DELICA D:2</b>	<b>2014</b>	<b>4</b>	
		<b>TOTAL</b>	<b>46</b>	

The affected parts shipped as spare parts, and could not possibility the vehicles equipped with them.

<b>PARTS NAME</b>	<b>PARTS NO</b>	<b>SHIPMENT YEAR</b>	<b>NUMBER OF PARTS</b>	<b>NOTE</b>
<b>Fuel Pump ASSY</b>	<b>15100-76R10</b>	<b>2019</b>	<b>1</b>	<b>XBEE</b>
	<b>15100-54860</b>	<b>2018</b>	<b>1</b>	<b>SOLIO</b>
	<b>15100-61P10</b>	<b>2019</b>	<b>1</b>	<b>SWIFT</b>
		<b>TOTAL</b>	<b>3</b>	