

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 4 4 3	DATE	Feb. 1. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In some fuel tanks, components on the upper surface of the fuel tank are not welded properly due to improper manufacturing processes. Therefore, there is a risk that a part of the weld is peeled off due to vehicle vibration in the process of using, and when the fuel is filled up, fuel may leak from the welded part.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
5 BA-TNE 5 2	EL GRAND	2 0 2 2 ~ 2 0 2 3	2 9
5 BA-PNE 5 2			8
5 BA-TE 5 2			7 1
5 BA-PE 5 2			8
		TOTAL	1 1 6