

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

| | | | |
|-----------------------|--|------|--------------|
| CAMPAIGN No. | 5446 | DATE | Feb 13, 2024 |
| MANUFACTURER | Komatsu Ltd. | | |
| DESCRIPTION OF DEFECT | In the hydrostatic transmission of a shovel loader, the consideration for the infiltration of rainwater and the like into the forward and reverse solenoids is insufficient, and there are no instructions for the direction of the solenoid lead wire extraction, resulting in some lead wires being installed upwards. Therefore, if continued to be used as is, the rainwater and the like adhering to the extraction port may infiltrate into the solenoid and cause rust, which in the worst case, could lead to a wire breakage and render the vehicle inoperable. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| WDR-WA126 | WA200-7 | 2014-2017 | 925 |
| YDR-WA137 | WA200-8 | 2017-2023 | 1434 |
| TOTAL | | | 2359 |