

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5450	DATE	February 13, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The side cover fixing pin may not normally fit in the latch due to improper structure of engine side cover on excavators or loaders. If the machine is continued to be used as it is, the pin may come off the latch due to operation vibration, and the side cover may fall off the machine in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	"WA470-10"	2019 - 2023	53
		TOTAL	53