

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5451	DATE	February 13, 2024
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The hydraulic piping in excavators or loaders may resonate with the transmission vibration and crack due to insufficient strength of its elbows or brackets. If the machine is continued to be used as it is, the hydraulic oil leaks from a crack in one elbow. Alternatively, one bracket may break and fail to fix the hydraulic piping. In the worst case, the hydraulic piping may crack and much hydraulic oil may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	"WA470-10"	2019 - 2023	51
		TOTAL	51