

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5453	DATE	Feb.15 2024
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>In the high-pressure fuel pump for some heavy-duty trucks and buses, the sliding surfaces between the tappet and roller and between the roller and cam can wear due to insufficient fuel film thickness that lubricates these surfaces. When this happens, the pump stroke can be reduced, or the fuel filter can become clogged with wear debris, causing insufficient fuel supply. In the worst case, this can result in a sudden engine stall or the inability to restart the engine.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FV70HJR	「FUSO SUPER GREAT」	2017~2019	350
2KG-FV70HX		2018~2019	52
2KG-FV70HYP		2019~2019	16
2KG-FV70HZP		2019~2019	2
2KG-FV74HJR		2018~2019	47
2PG-FS70HZ		2017~2019	575
2PG-FS74HY		2017~2019	88
2PG-FS74HZ		2017~2020	6,214
2PG-FS75HY		2019~2019	2
2PG-FS75HZ		2017~2020	806
2PG-FU70HY		2017~2019	154
2PG-FU74HY		2017~2019	117
2PG-FU74HZ		2017~2020	2,570
2PG-FU75HZ		2017~2019	484
2PG-FV70HX		2017~2020	1,708
2PG-FV70HY		2017~2019	409
2PG-FV70HZ		2017~2019	539
2PG-FV74HJR		2018~2019	40
2PG-FV74HZ		2017~2019	381
2PG-FY70HY		2017~2019	88
2PG-FY74HY		2017~2019	154
2RG-FP74HDR		2017~2020	1,319
2RG-FP74HER		2017~2019	550
2RG-FP74HGR		2017~2019	81
QKG-FU60VY		2017	1
QKG-FV60VJR		2017~2018	309
QKG-FV60VX		2017~2017	30
QKG-FV60VY		2017~2017	20
QKG-FV60VZ		2017	1
QKG-FV64VJR		2017~2017	5

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-FP64VDR		2017~2018	326
QPG-FP64VER		2017~2018	91
QPG-FP64VGR		2017~2018	35
QPG-FS60VZ		2017~2017	6
QPG-FS64VY		2017~2017	14
QPG-FS64VZ		2017~2017	254
QPG-FS65VY		2017	1
QPG-FS65VZ		2017~2017	54
QPG-FU60VY		2017~2017	12
QPG-FU60VZ		2017	1
QPG-FU64VY		2017~2017	11
QPG-FU64VZ		2017~2017	168
QPG-FU65VZ		2017~2017	14
QPG-FV60VX		2017~2017	37
QPG-FV60VY		2017~2017	6
QPG-FV60VZ		2017~2017	9
QPG-FV64VJR		2017~2017	8
QPG-FV64VZ		2017~2017	12
QPG-FY60VY		2017~2017	12
QPG-FY64VY		2017~2017	11
QTG-MS96VP	「FUSO AERO ACE」	2017~2017	2
	「FUSO AERO QUEEN」	2017~2017	4
		TOTAL	18,200

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS	
2PG-FS75HZ	「FUSO SUPER GREAT」	2017～2017	1		
2PG-FU75HZ		2017～2017	1		
QDG-FV50VJR		2013～2013	1		
QKG-FP54VDR		2014～2014	2		
QKG-FS54VZ		2013～2013	1		
QKG-FV60VJR		2014～2014	10		
QKG-FV60VX		2015～2016	8		
QKG-FV60VY		2015～2016	3		
QPG-FP64VDR		2015～2017	11		
QPG-FP64VER		2015～2017	4		
QPG-FP64VGR		2016～2016	1		
QPG-FS64VZ		2015～2015	2		
QPG-FS65VZ		2016～2017	2		
QPG-FU64VZ		2015～2017	8		
QPG-FU65VZ		2016～2016	2		
QPG-FV60VZ		2015～2015	1		
QRG-MS96VP		「FUSO AERO ACE」	2015～2017		28
		「FUSO AERO QUEEN」	2015～2017		11
TOTAL			97		

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	REMARKS
6R10・20 Engine Assy	6R10-064775	2017~2019	45	
	6R10-064781			
	6R10-064782			
	6R10-064891			
	6R10-064996			
	6R10-065097			
	6R10-065104			
	6R10-065109			
	6R10-065122			
	6R10-065123			
	6R10-065128			
	6R10-065154			
	6R10-065156			
	6R10-065221			
	6R10-065222			
	6R10-065251			
	6R10-065255			
	6R10-065411			
	6R10-065414			
	6R10-065577			
	6R10-065738			
	6R10-065769			
	6R10-065844			
	6R10-065845			
	6R10-065847			
	6R10-065848			
	6R10-065850			
	6R10-065860			
	6R10-065863			
	6R10-065865			
	6R10-065866			
	6R10-065872			
	6R10-065875			
6R10-065878				
6R20-002719				
6R20-008488				
6R20-013509				
6R20-013955				
6R20-014673				
6R20-015004				
6R20-015229				
6R20-015230				
6R20-015621				
6R20-015687				
6R20-017750				
High Pressure Pump	MX910559		168	
	MX910688		821	
		TOTAL	1,034	