

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5459	DATE	Feb.28.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>Due to incorrect programming of the illumination control for the brake warning light in the combination meter, the brake warning light will not illuminate during the system check when the engine is started. In addition, if the brake system has a malfunction during usage of the vehicle, the ABS warning light and the slip indicator light will illuminate along with the warning message in the center of the combination meter, but the brake warning light will not illuminate.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-KSP210	[YARIS]	2024	35	gasoline engine vehicle
5BA-MXPA10			21	
5BA-MXPA15			10	
5BA-MXPB10	[YARIS CROSS]		55	
5BA-MXPB15			25	
		TOTAL	146	