

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5458	DATE	February 29,2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the connector for connecting the brake piping, due to improper management of the manufacturing facility, the machining accuracy is poor, there are those connecting portion with the brake piping has a poor adhesion. Therefore, if it continues to be used as it is, the brake fluid leaks from the seal part of the connector, the brake warning light will turn on, and in the worst case, there is a risk that the braking distance may be extended.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U68V	「MINICAB-MiEV」	2023	487
		TOTAL	487