VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2500	DATE	Apr.6.2010	
MANUFACTURER	NISSAN			
DESCRIPTION OF DEFECT	NISSAN Due to a disc in the device adjusts the operation force of the accelerator pedal was reminded the oil for the forming process, the friction against the plate may increase while the vehicle continue to use. If the disc continues to use, a response of the throttle angle sensor may delay. In an extreme case, the engine revolutions cannot return to the revolution of idle. The affected vehicles were equipped the brake precedence control, therefore the vehicle can be automatically shut the throttle by putting on the brakes and can be stopped in this condition.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
G F – P A 3 3	CEFIRO	$ \begin{array}{c} 1998 \\ \sim \\ 2002 \end{array} $	10,775
G F – Q U 1 4	BLUEBIRD		2, 635
G F – Q B 1 5	SUNNY		2, 570
G F – Q P 1 1	P R I ME R A		2, 613
G F – WQ P 1 1			6, 317
HN-PV10	ΤΙΝΟ		114
		TOTAL	25,024