

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2507	DATE	April 8 . 2010	
MANUFACTURER	Komatsu Utility Co. , Ltd.			
DESCRIPTION OF DEFECT	<p>1)Due to improper electric circuit, if a lump on a monitor has a trouble, alternator can not charge electricity. Therefore if a machine is used under its condition, engine may not be able to start again.</p> <p>2)Due to improper engine electric circuit, engine injection condition may not be normal. Therefore if a machine is used under its condition, emission could not meet with regulation.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KDN-M231	FD30H,FD35A	2009~2010	7	
EDM-SM228	FD20,FD25	2009~2010	93	
EDM-M228	FD25	2009~2010	4	
EDM-SM229	FD30	2009~2010	10	
EDM-M229	FD30	2009	2	
		TOTAL	116	