

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2498	DATE	April 8,2010
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	IN THE REAR DIFFERENTIAL, WRONG BOLTS HAVE BEEN USED TO TIGHTEN THE REAR COVER OF THE REAR DIFFERENTIAL. IF USE CONTINUES UNDER THIS CONDITIONS, THE SUBJECT BOLT COULD BE LOOSENED RESULTING IN THE OIL LEAKAGE AND IN A WORST CASE SCENARIO, THE VEHICLE COULD BE UNABLE TO BE DRIVEN.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-V83W	P A J E R O	2010	9
ADC-V88W		2010	2
DBA-V93W		2010	30
CBA-V97W		2010	2
ADC-V98W		2010	13
KH-V78W	P A J E R O	AFFECTED REAR DIFFERENTIAL WAS SHIPPED AS A SERVICE PART AND INSTALLED IN THE VEHICLE ON MARCH 4, 2010.	1
TOTAL			57