## VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic (Import \	/ehicles

CAMPAIGN No.	Gai — 1 6 5 9	DATE	April.8.2010
MANUFACTURER	VOLVO LOGISTICS	CORPORATION JAPA	N CO., LTD.
DESCRIPTION OF DEFECT	Due to inappropriate heat treatment on the spline yoke of propeller shaft, some of propeller shafts do not have enough strength. Therefore, it might cause crack, and the propeller shaft drop out in the worst case if the vehicle is being operated in this condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Fumei	_	1999	49
		TOTAL	49