

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2509	DATE	Apr.13.2010
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain light buses, due to inadequate spot welding of the protector for the air spring at the rear left position, the spot welded area may separate caused by the vibration during driving etc, allowing the subject protector come off the vehicles.		

TYPE	door	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-RX6JFBA	Hino Liesse	2010	16
		TOTAL	16