VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2510	DATE	April 13 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain light buses, due to inadequate spot welding of the protector for the air spring at the rear left position, the spot welded area may separate caused by the vibration during driving etc, allowing the subject protector come off the vehicles.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
BDG-RX6JFBJ	ISUZU JOURNEY J	2010	2
		TOTAL	2