

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2511	DATE	April 13, 2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to insufficient strength of joint part of front drive, which transfers torque from transmission to front axle, a crack may happen. Therefore is a machine is used continuously, a shaft might be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-WA096	WA500-6	2005 ~ 2010	6
TOTAL			6