

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2516	DATE	April 13, 2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to lack of wear resistance of ball, which is a support of locker cam to control oil flow inside hydraulic pump, ball wear may happen. Therefore if a machine is continuously used, oil flow is decreased and in the worst case, an operator can not control steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-WA098	WA470-6	2006 ~ 2010	17
	WA480-6	2006 ~ 2010	7
JDS-WA096	WA500-6	2005 ~ 2010	6
TOTAL			30