

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2513	DATE	April 15 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In the H/D buses, it has been found that underfloor harness arrangement was inadequate, with a result that the harness rubbed against the pipe mounting bracket. Thus, if they are used as are, the harness cover may be damaged due to vehicle vibration, etc. In the worst case, the engine may be stalled and the lamps, etc., may be unlighted.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-LV774R2	GALA	2002-2005	111
		TOTAL	111