

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2514	DATE	April. 15. 2010
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The rear wheel brake light switch may be inadequate in waterproof structure. Such a switch becomes hot as is exposed to heat from the catalytic converter and will cool as is exposed to water, when the water seeps in through the switch cover and the internal contact points can be thereby rusted, resulting in poor continuity. Should this happen, the brake light could fail to come on when the rear wheel brake is applied.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-NC42	CB400	2007~2008	4,261
	SUPER FOUR	2008	1,457
	/		
	CB400	2008~2010	5,160
	SUPER BOLD 'OR	2010	948
		TOTAL	11,826