

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2523	DATE	April. 22. 2010	
MANUFACTURER	KUBOTA Corporation			
DESCRIPTION OF DEFECT	The bolts of the support joint cover which fix the steering joint on the tractor may not be tighten enough. That makes the unsteady steering joint movement.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
BR	KB17X	2010	3	
	KB17XF	2010	1	
BS	KB19X	2010	5	
BT	KB21X	2010	52	
	KB21XF	2010	6	
BU	KB23X	2010	3	
	KB23XF	2010	1	
TOTAL			71	