## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

Donlestic Vehicles				
CAMPAIGN No.	2520	DATE	Apr. 23. 2010	
MANUFACTURER DESCRIPTION OF DEFECT	ShinMaywa Industries, Ltd.  Inappropriate way of installing spacer to the cross-member was applied to tail gate lifter equipped truck.  (For the purpose of adjusting the height of spare tire position.)  As a result, there are possibilities that crack may occur in the cross-member by vibration of the truck.  In the worst case, the spare tire may drop off.			
TYPE	COMMERCIAL NAME		MODEL YEAR CALLED	NUMBER OF VEHICLE
BDG — SZ2F24	ATLAS		2008	2
CBF — SQ1F24		200	07~2008	3
CBF — SQ2F24		200	07~2009	18
PDG — SZ2F24		200	07~2009	44
PDG — SZ5F24		200	07~2009	8
PDG — TZ2F24		200	07~2009	13
PDG — ASZ2F24	ELF		2007	1
CBF — ASQ2F24		200	08~2009	2
		-	TOTAL	91