

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2529	DATE	May 11 . 2010	
MANUFACTURER	Komatsu Utility Co. , Ltd.			
DESCRIPTION OF DEFECT	<p>The terminal of the electrical wiring harness connected with the alternator might be broken by the vibration at the connected portion due to improper routing of the harness.</p> <p>Therefore, if it is used under such a condition continuously, electricity might not be able to be charged to the battery.</p> <p>Then the engine might not be able to be started in the worst case.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
KDN-M231	FD30H,FD35A	2009~2010	7	
EDM-SM228	FD20,FD25	2009~2010	124	
EDM-M228	FD25	2009~2010	5	
EDM-SM229	FD30	2009~2010	12	
EDM-M229	FD30	2009~2010	5	
		TOTAL	153	