

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2528	DATE	May 13,2010
MANUFACTURER	Mazda E&T Co.,Ltd.		
DESCRIPTION OF DEFECT	On some Axela (Japan) driving school spec. vehicles with optional horn switch for instructor, horn may not be blown by driver's horn switch due to bad electrical contact caused by wrong connector installed for the optional horn switch and vibration while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-BL6FJ	Mazda Axela	2009 – 2010	232
TOTAL			232