

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 5 3 0	DATE	May 13, 2010
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Strength of idle roller in endless rubber crawler installed on Driving equipment of Agricultural Tractor is not enough. In case of snow or mud on idle roller and if it cause crawler tension bigger, bearing area could be broken. Therefore, there is a possibility that endless crawler come off, tractor can not be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
SB-T150F	TJ75AT TJ65AT TJ55AT	2007-2010	298
SB-T150F	CT75H CT65H CT55H	2007-2010	37
SB-T151F	TJ85	2007-2010	211
SB-T151F	CT85H	2007-2010	15
		TOTAL	561