

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2 5 3 3	DATE	May 13, 2010
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	Strength of fuel tank of fuel equipment for Agricultural tractor is not enough. It could cause tank deformation by unstable assembly or crack by vibration during driving, therefore there is a possibility of fuel leakage from tank. Fixed band for fuel tank is fastened too tight, if operator use with this condition, there is a possibility of fixed band breakage and unusual noise.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
T131F	TJ75	2001-2003	387
T137F	TJ75	2003	263
SB-T137F	TJ75 TJ65 TJ55	2003-2005	788
SB-T150F	TJ75AT TJ65AT TJ55AT	2005-2007	940
SB-T150F	CT75H CT65H CT55H	2006	17
SB-T151F	TJ85	2006-2007	315
		TOTAL	2710