

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2 5 3 2	DATE	May 14, 2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Insufficient capacity fuse has been installed on optional large capacity alternator equipped vehicle and if electrical currency exceeded, the fuse blows. In this case, there is a risk to stall engine and to become it is impossible to restart the engine due to lack of battery charges by the blown fuse.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SC-GD013A	GD655-3	2006 ~ 2007	25
TOTAL			25