

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2541	DATE	May 21, 2010
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Due to improper manufacturing process of accelerator return spring which is applied in a accelerator pedal, strength of return spring may be insufficient.</p> <p>Therefore if a machine continuously used, breakage of spring may happen, and accelerator pedal might not return in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-WA105	WA200-6	2007~2010	234
EDR-WA103	WA270-6	2007~2010	149
EDR-WA108	WA320-6	2007~2010	109
JDS-WA095	WA380-6	2006~2010	61
JDS-WA091	WA430-6	2006~2010	27
JDS-WA098	WA470-6	2006~2010	9
	WA480-6	2006~2010	4
JDS-WA096	WA500-6	2006~2010	3
JDS-GD024	GD755-5	2008~2010	36
	GH320-5	2008~2010	16
TOTAL			648