

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2542	DATE	May 21, 2010
MANUFACTURER	Komatsu Utility Co., Ltd.		
DESCRIPTION OF DEFECT	<p>Due to improper manufacturing process of accelerator return spring which is applied in a accelerator pedal, strength of return spring may be insufficient.</p> <p>Therefore if a machine continuously used, breakage of spring may happen, and accelerator pedal might not return in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-M246	FD115,FD120	2008	8
EDR-M246	FD100	2009	1
EDR-M247	FD135,FD150E, FD160E	2008~2009	9
KDP-M248	FD60,FD70, FD80	2008~2010	12
KDP-M250	FD35N,FD40N	2008~2009	11
KDP-M252	FD35,FD40, FD45,FD50A	2008~2009	41
TOTAL			90