

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2537	DATE	May 25 . 2010
MANUFACTURER	Komatsu Utility Co. , Ltd.		
DESCRIPTION OF DEFECT	Due to insufficient strength of piston seals, which is installed to power steering cylinder of rear axle, internal oil spill may happen. Therefore steering performance of vehicle might not be able to satisfy the safety requirement.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-M250	FD35N,FD40N	2008~2009	11
KDP-M252	FD35,FD40,FD45,FD50A	2008~2009	41
EBP-M251	FG40N	2009	1
		TOTAL	53