

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2545	DATE	May.27 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some vehicles, the oil hole for worm shaft in the power steering gearbox was made improperly. If turning at low speeds and steering at standstill are repeated, the steering force may become heavier.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-FE73B	FUSO CANTER	2009~2009	4
PDG-FE71BD		2009~2009	6
PDG-FE71DD		2009~2009	25
PDG-FE73B		2009~2009	5
PDG-FE73D		2009~2009	42
PDG-FE73DN		2009~2009	8
PDG-FG73D		2009~2009	10
PDG-FG83D		2009~2009	3
BKG-FE71BSD		2009~2009	20
		TOTAL	123