

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 5 4 9	DATE	June 2, 2010
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>As the plastic material of outer race of tensioner pulley which adjusts the belt tension of power steering pump is improper, the plastic part may break down making abnormal noise.</p> <p>In the worst case, the steering may become heavy as the belt comes out from the pulley.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-TA74W	Escudo	2006	50
CBA-TD94W		2005~2006	2,575
ABA-JB43W	Jimny	2005	348
		2005~2006	743
		TOTAL	3,716